Raport Historii Pojazdu autoDNA



Renault Master

VF1VB000472613011

ON Diesel

Zeskanuj i zobacz raport online

Ostatni stan drogomierza **113 329 km**

Ubezpieczenie do **2029-08-11**

Raport zawiera dostępne informacje na dzień: 2026-11-26 16:10:11 UTC +0100 Wersja językowa PL
048d7ddc-cd7e9a15-747fba93-90176078-6c869100

Aby sprawdzić oryginalność raportu, zeskanuj kod QR widoczny w nagłówku.

Kluczowe informacje

- Uszkodzenie
- Brak szkody całkowitej
- Brak rozbieżności drogomierza
- Krajowy
- Więcej niż jeden właściciel

Przegląd historii

Kradzież	Nie odnotowano	Zastaw skarbowy	Nie odnotowano
Uszkodzenie	Odnotowano	Rozbieżność drogomierza	Nie odnotowano
Szkoda całkowita	Nie odnotowano	Specjalne przeznaczenie	Nie odnotowano
Akcja serwisowa	Nie odnotowano	Niedopuszczony do ruchu	Nie odnotowano
Złomowanie	Nie odnotowano	Historia serwisowa	Posiada

Skrótowe podsumowanie informacji o historii pojazdu. Zielone pozycje to dla kupującego sygnał, że auto nie kryje nieprzyjemnych niespodzianek w bazach autoDNA — a dla sprzedającego argument, który buduje zaufanie i przyspiesza transakcję.

Nawigacja raportu

- **Informacje o pojeździe** — Liczba wpisów: **11**
- **Akcje serwisowe** — Liczba wpisów: **0**
- **Bazy skradzionych pojazdów** — Przeszukane bazy: **14/14**
- **Odczyty drogomierza** — Liczba wpisów: **4**
- **Historia pojazdu** — Liczba wpisów: **14**
- **Dziennik sprawdzeń** — Liczba wpisów: **0**
- **Wyposażenie** — Liczba wpisów: **215**
- **Archiwalne zdjęcia** — Liczba wpisów: **0**

Informacje o pojeździe

Renault • Master

Typ paliwa **DIESEL**	Pojemność silnika [cm3] **2300**	Kolor lakieru **WHITE**
Data produkcji **2024**	Moc silnika **121KW (164HP)**	Układ kierowniczy **LEWOSTRONNY**
Typ skrzyni biegów **MANUALNA**	Napęd **FWD**	Liczba biegów **6**
Norma emisji spalin **EURO 6**		

Akcje serwisowe

Sprawdzone, nie odnotowano danych

Bazy skradzionych pojazdów

Przeszukane bazy **14** | Nie odnotowano

Włochy
Ewidencja pojazdów skradzionych - Policja

Nie odnotowano

Czechy
Ewidencja pojazdów skradzionych - Policja

Nie odnotowano

Rumunia
Ewidencja pojazdów skradzionych - Policja

Nie odnotowano

Litwa
Ewidencja pojazdów skradzionych - Policja

Nie odnotowano

Słowenia
Ewidencja pojazdów skradzionych - Policja

Nie odnotowano

Holandia
Ewidencja pojazdów skradzionych - Repozytoria Crimimail oraz Stowarzyszenie Ubezpieczycieli

Nie odnotowano

Kanada
Ewidencja pojazdów skradzionych - Policja

Nie odnotowano

Słowacja
Ewidencja pojazdów skradzionych - Policja

Nie odnotowano

Szwecja
Ewidencja pojazdów skradzionych - Stowarzyszenie Ubezpieczycieli

Nie odnotowano

Norwegia
Ewidencja pojazdów skradzionych - Ettersokt

Nie odnotowano

Kaynine
Ewidencja przedmiotów skradzionych - Kaynine (Niemcy)

Nie odnotowano

Baza int.
Ewidencja pojazdów skradzionych - Niezależne źródła internetowe

Nie odnotowano

Polska
Baza skradzionych pojazdów - PL

Nie odnotowano

Węgry
Baza skradzionych pojazdów - HU

Nie odnotowano

Odczyty drogomierza



Cel sekcji:
Wykres prezentuje historyczne odczyty drogomierza – są to „zdjęcia z przeszłości, nie stanowią one ciągłego monitoringu przebiegu pojazdu”

Zasady interpretacji przebiegu:
Wykres prezentuje historyczne odczyty drogomierza zarejestrowane podczas przeglądów, serwisów, aukcji lub rejestracji, do których AUTODNA miało dostęp na moment wygenerowania raportu.

- **Trend rosnący:** Prawidłowa historia powinna wykazywać stały wzrost wartości.
- **Analiza rozbieżności:** Wszelkie spadki lub nielogiczne skoki mogą wynikać na przykład z błędnych odczytów, błędów przy wprowadzaniu danych (tzw. „czeski błąd”), wymiany licznika lub celowej manipulacji.
- **Weryfikacja:** W przypadku wątpliwości zaleca się porównanie danych z fizyczną książką serwisową pojazdu oraz weryfikację stanu zużycia podzespołów przez rzeczoznawcę.
- **Uwaga:** Brak wpisów w danym okresie nie oznacza braku eksploatacji pojazdu.

Historia pojazdu

2028

12.08.2028

Ubezpieczenie pojazdu

Polisa ważna do **2029-08-11**

Kraj **Polska**

2026

05.2026

Odnotowano szkodę na pojeździe

Kwota **1 000 - 1 100 PLN**

Rezultat

USZKODZENIE SZYB

Grupa części
- Szyby



Strefa uszkodzenia
- Przód

Kraj **Polska**

02.2026

Serwis lub kontrola pojazdu

Serwis regularny
Wymiana filtra kabinowego
Wymiana filtra powietrza silnika

Kraj **Polska**

2025

11.2025

Serwis lub kontrola pojazdu

Stan drogomierza
113 329 km

Serwis regularny
Wymiana filtra kabinowego
Wymiana filtra paliwa
Serwis układu przeniesienia napędu
Wymiana filtra powietrza silnika

Kraj **Polska**

06.2025

Serwis lub kontrola pojazdu

Stan drogomierza
58 214 km

Wymiana filtra paliwa
Wymiana oleju
Wymiana filtra powietrza silnika

Kraj **Polska**

04.2025

Serwis lub kontrola pojazdu

Stan drogomierza
42 524 km

Serwis regularny
Wymiana filtra kabinowego

Kraj **Polska**

02.2025

Serwis lub kontrola pojazdu

Stan drogomierza
19 897 km

Serwis regularny
Wymiana filtra kabinowego

Kraj **Polska**

2024

14.08.2024

Rozpoczęcie okresu gwarancyjnego

12.08.2024

Pojazd zarejestrowany

Zarejestrowany na firmę lub organizację
Miejsce rejestracji **Jaworzno, śląskie**

Nowy, zakupiony w kraju
Homologowany fabrycznie
Termin badania technicznego **2027-08-11**

Kraj **Polska**

12.08.2024

Przerejestrowanie pojazdu, ze względu na zmianę własności

Zarejestrowany na firmę lub organizację
Miejsce rejestracji **Olsztyn, warmińsko-mazurskie**

Kraj **Polska**

27.03.2024

Ubezpieczenie pojazdu

Polisa ważna do **2024-04-25**

Kraj **Polska**

27.03.2024

Pojazd zarejestrowany

Zarejestrowany na firmę lub organizację
Miejsce rejestracji **Jaworzno, śląskie**

Nowy, zakupiony w kraju
Homologowany fabrycznie
Termin badania technicznego **2027-03-26**

Kraj **Polska**

27.03.2024

Pierwsza rejestracja pojazdu

02.2024

Pojazd wyprodukowany

Lokalizacja **Batilly**

Kolor nadwozia **Biały**
Kierownica z lewej strony
Brak haka holowniczego
Koło zapasowe dojazdowe

Kraj **Francja**

Zasady interpretacji danych:

Zdarzenia nieodnotowane:
Pojazd mógł uczestniczyć w kolizjach lub naprawach, które nie zostały zgłoszone do systemu autoDNA lub miały miejsce w regionach nieobjętych raportowaniem.

Rekomendacja:
Raporty autoDNA oraz informacje w nich zawarte powinny być traktowane jako wskazówka oraz stanowić jeden z kroków związanych z zakupem/sprzedażą pojazdu. Informacje zawarte w raportach należy weryfikować w ASO oraz podczas szczegółowych oględzin eksperta. Raporty autoDNA są narzędziem pomocniczym.

Dziennik sprawdzeń

- Sprawdzone, nie odnotowano danych

Wyposażenie

PASSENGER COMPARTMENT THERMAL REQUIREMENT: PASSENGER COMPARTMENT THERMAL REQUIREMENT 1	TYPE OF FRONT WINDOW WINDER.: DRIVER: ANTI-PINCHING PULSED / PASSENGER: MOTOR UNIT	FRONT PASSENGER SEAT ADJUSTMENT: MULTI-FUNCTION PASSENGER BENCH SEAT TYPE 4
COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION: TECHNICAL REG: POLAND	SPECIAL EDITIONS/ADDITIONAL EQUIPMENT: EQUIPEMENT PRODUCT H01	TRANSPORT OR PARTNER VEHICLE TYPE: WITHOUT VEHICLE ADAPTATIO
ADJUSTMENT OF FRONT SEAT BELTS: HEIGHT ADJUSTABLE SEATBELTS	LIMITED EDITION ADDITIONAL DEFIN: WITHOUT DEFINITION SUPPLE	DOOR OPENING REMOTE CONTROL TYPE: 315 MHZ NORMAL DOOR OPENI
SUPPLEMENTARY CONVERSION: WITHOUT SUPPLEMENTARY CONVERSION	DRL W SIGNATURE IGNITION FRT RR: DAYTIME RUNNING LIGHTS 2	WIPER START-UP TYPE: AUTOMATIC LIGHTS + WINDSCREEN WIPER
COMMERCIAL VERSION SUPPLEMENT: BASIC COMMERCIAL VERSION	REAR SEATS ADDITIONAL HEATING: WITHOUT REAR SEAT HEATING	TYPE OF UTILITY VEHICLE REAR DOORS: WITHOUT REAR SUNROOF
ELECTRONIC STABILITY PROGRAM: DIRECTIONAL STABILITY CON	FRONT AND REAR PROXIMITY RADAR: WITHOUT PROXIMITY RADAR	ELECTRIC VEHICLE BATTERY CHARGING: COMPLEMENTARY OBJECT
VEHICLE HEIGHT LEVEL ADJUSTER: NON-PNEUMATIC SUSPENSION	ADDITIONAL ENGINE ENVIRONMENT: WITHOUT FILTER DECANTER	UTILITY ADAPTATION COVER SPECIFI: COMPLEMENTARY OBJECT
PLANT MARKING FOR COMPLEX START: COMPLEMENTARY OBJECT	NAVIGATION/SMARTPHONE IMITATION: COMPLEMENTARY OBJECT	EMISSION REDUCTION SERVICE: EMISSION REDUCTION SERV 3
ON-BOARD WARRANTY/SERVICES: RENAULT SANS CE REGION A1	EMERGENCY CALL AND BREAKDOWN: WITHOUT CALL FONCTION	PASSENGER COMPARTMENT HEATING TYPE: AIR-CONDITIONING
IN USE PERFORMANCE RATING: WITH IN USE PERFORMANCE R	EMISSION CONTROL STANDARD: EURO6 S10 DIESEL OBD IUPR	BATT CHARGE CABLE M2 AND ADAPT: COMPLEMENTARY OBJECT
SPECIAL BUILD (FACTORY).: SERIES VEHICLE (WITHOUT S	GEARBOX TYPE/NUMBER OF GEARS: 6-GEAR MANUAL GEARBOX	ADDITIONAL HEADLIGHTS: WITHOUT ADDITIONAL HEADLIGHT
ELECTRIC TOLL COLLECTION: WO ELECTRONIC TOLL SYS SP	FORWARD EMERGENCY BRAKING: WITHOUT URB ADV EM BRAKE	SUPPLEMENTARY CHILD PACK: WITHOUT CHILD PACK SUPPLE
UTILITY ADAPTATION INTEG. PARTI*: CONTEXT CRITERIOM	INTERIOR CARGO SIDE TRIM: WITHOUT INTERIOR SIDE LIN	SHELF OF PANEL INSTRUMENT: SHELF PANEL INSTRUMENT 1
STAND FOR TABLET COMPUTER: WITHOUT STAND FOR TABLET	TYRE PRESSURE DETECTION: WITHOUT TYRE PRESSURE DET	EXTERIOR REAR VIEW MIRRORS: 2 ELEC OUTSIDE MIRRORS
VEHICULE TRANSFORMATION: WO VEHICULE TRANSFORMATIO	POWER TAKEOFF ON ENGINE: WITHOUT POWER-TAKE OFF ON	MISCELLANEOUS BENEFITS : MASSES: CONTEXT CRITERIOM
INVARIANT PROCESS SHEET MODEL: MODEL ROUTING SHEET	UTILITY ADAPT COVER QSTOMIZE: COMPLEMENTARY OBJECT	VEHICLE LIGHT CONVERSION: WO LIGHT ADAPTATION SVO
VARIOUS ADDITIONAL FEATURES: COMPLEMENTARY OBJECT	TRANSMISSION TYPE: FRONT WHEEL DRIVE TRANSMISSION	POWER TAKE-OFF ON GEARBOX: WITHOUT POWER TAKE-OFF
WHEEL DISC PROTECTION.: PROTECTIVE REAR BRAKE DIS	REAR CONNECTION DEVICE: WO ADAPTATION CONNECTION	EXT MIRROR PROJECTION: EXTERIOR REAR VIEW MIRROR
TYPE APPROVAL CATEGORY: APPROVAL TYPE N1 CLASS 3	UTILITY ADAPT COVER QSTOMIZE: WITHOUT ADAPTATION	SMOKER'S ACCESSORIES: WITHOUT SMOKER ACCESSORIE
LEVEL OF NAVIGATION AID: WITHOUT NAVIGATION AID	GEAR SHIFT INDICATOR: WITH GEAR SHIFT INDICATOR	WIRELESS PHONE CHARGE: WO TELEPHONY ACCES REFIL

BLIND SPOT DETECTION: WITHOUT DECTECTOR BLIND S	WIDE ANGLE REAR VIEW: WITHOUT BUS REAR VIEW MIR	REAR EXTENDED WIRING: WHITHOUT WIRING LENGTHENS
INTERIOR REAR VIEW MIRROR: COMPLEMENTARY OBJECT	BATTERY POWER TRACTION: WIHTOUT BATTERY ENERGY	REAR DIFFERENTIAL LOCK: WITHOUT REAR DIFF LOCK
BATTERY INDEX TRACTION: WITHOUT BATTERY SUFFIX	BRAKING ASSISTANCE: BOOSTER EMERGENCY BRAKING	ANTI-THEFT DEVICES: WITHOUT ANTI-THEFT DEVICE
BATTERY LEVEL TRACTION: WITHOUT BATTERY LEVEL	REAR TOWING DEVICE: WITHOUT REAR TOWING DEVIC	PARKING BRAKE TYPE: WITHOUT AUTOMATIC PARKING
UPPER DASHBOARD STORAGE: WO DASHBOARD STORAGE	CERTIFICATION EVOLUTION: COMPLEMENTARY OBJECT	PARTS MANUFACTURER SERVICE: CONTEXT CRITERIOM
ENGINE POWER CUT DOWN CONTROL: POWER CUT DOWN	DOCUMENTATION PERIOD: DOCUMENTARY PERIOD 2020	INTERIOR LIGHTING CARGO: COMPLEMENTARY OBJECT
SEAT BELT REMINDER: DR AS REAR SEAT BELT REMI	INTERIOR COLOUR STYLING: INTERIOR HARMONY 01	UNDERBODY PROTECTION: WO ANTIGRIT PROTECTION
UNIVERSAL INTERCONNECT FUNCTION: WITHOUT TCU	VEHICLE TRACKING SYSTEM: W/O SECURITY DEVICE	FRONT SIDE AIRBAG: WITHOUT FRONT SIDE AIRBAG
ENGINE HEATING ELEMENT: COMPLEMENTARY OBJECT	FIRE EXTINGUISHER: WITHOUT EQUIPMENT LEVEL O	TRACTION BATTERY CONTRACT: CONTEXT CRITERIOM
TYPE OF PARTITION: COMPLETE BULKHEAD WITH WI	MOTOR ENERGY EQUIPMENT: COMPLEMENTARY OBJECT	DRIVER'S HANDBOOK: POLISH GLOVE BOX LITERATU
TECHNICAL EVOLUTION A: COMPLEMENTARY OBJECT	INTERIOR ROOF TRIM: WITHOUT ROOF TRIM STYLE	IDLE SPEED CONTROL: WITHOUT FAST IDLE SPEED
GEARBOX TYPE: 6-SPEED MANUAL GEARBOX – BVM6	RIGHT-HAND SIDE SECTION: NO RIGHT SIDE DOOR	TECHNICAL EVOLUTION N: COMPLEMENTARY OBJECT
DRIVER SEAT TYPE: DRIVER SEAT WITH LUMBAR A	PARTITION INSULATION: PARTITION TRIM TYPE 1	WIRING FOR CONVERSION: WITHOUT WIRING ADAP.
CENTRAL DOOR LOCKING: ELECTRIC DOOR LOCKING	DOCUMENTATION PHASE: DOCUMENTATION PHASE 2	STORAGE FOR ACCESSORIES: CONTEXT CRITERIOM
UNDERBODY PROTECTION: COMPLEMENTARY OBJECT	ACCESSORY SOCKET: WITHOUT ACCESSORY SOCKET	WATER PROTECTION: WO RAIN FORD RIVER KIT
LOAD ANCHORING POINTS: NO ANCHORING POINT	ENGINE CAPACITY: 2300 CM3 ENGINE CAPACITY	TYPE OF DUMPER / TRAY: WITHOUT DUMP BODY
LEFT-HAND SIDE SECTION: NO LEFT SIDE DOOR	BIG TRUNK OPENING TYPE: CONTEXT CRITERIOM	CHILD SEAT PRE-EQUIPMENT: NON-ISOFIX SEAT
MAKE OF TYRES: TYRE BRAND: UNMARKED FITT	SEATS: 3RD ROW: 0 SEAT - THIRD ROW SEATS	GEOGRAPHIC COUNTRY: COMPLEMENTARY OBJECT
TYPE OF REFRIGERANT GAS: GAS TYPE 1234YF	SIDE DOOR OPENING: COMPLEMENT OBJECT 053	ADDITIONAL FLOOR: WITHOUT FLOOR ADDITIVE
TYPE OF BATTERY: NON-REINFORCED BATTERY	SEAT HEATER AND COOLER: NON-HEATED SEAT	VARIOUS FUNCTIONS: COMPLEMENTARY OBJECT
UTILITY VEHICLE WHEELBASE: WHEELBASE 30	REAR STEP BOARD: WITHOUT REAR SIDE SILL	SELECTIVE CATALYTIC REDUCTION: WITH SCR
CKD GROUPING ZONE: COMPLEMENTARY OBJECT	STARTUP CRITERIA: COMPLEMENTARY OBJECT	POLLEN/DUST FILTER: WITH POLLEN FILTER
ROAD SEVERITY: TYPE OF ROAD SEVERITY 1	PRESTATION EIGHT: COMPLEMENTARY OBJECT	REAR CARPET - FLOOR: CONTEXT CRITERIOM
LEVEL OF MOTORIZATION: AE ENGINE LEVEL	MISCELLANEOUS DIX: CHROME PRESTATION 3	INSTRUMENT PANELS: INSTRUMENT PANEL 09

COLOR OF BUMPERS: COMPLEMENTARY OBJECT	ADDITIONAL KEY: WITHOUT ADDITIONAL KEY	BATTERY TYPE TRACTION: WITHOUT BATTERY
PARTICLE FILTER: WITH PARTICLE FILTER	WHEEL RIM TYPE: 16 METAL WHEEL RIMS 1	SPECIAL CONVERSION: CONTEXT CRITERIOM
SPEED LIMITER.: WITHOUT SPEED LIMITER	SERVICE COUNTRY: COMPLEMENTARY OBJECT	SIDE STEP BOARD: COMPLEMENTARY OBJECT
MARKETING VERSION: COMMERCIAL VERSION	ELECTRICAL PACKAGE: CONTEXT CRITERIOM	SERVICE DONGLE: COMPLEMENTARY OBJECT
PLANT ASSEMBLY LINE: ASSEMBLY LINE 1	ROOF RACK/BARS: COMPLEMENTARY OBJECT	SEAT COVERS: FABRIC SEAT-LINING N 07
POWER STEERING: COMPLEMENTARY OBJECT	AIRBAG CANCEL: DECONNEX AIRBAG PASS	STOP AND START: WITH STOP AND START
EQUIPMENT LEVEL: EQUIPMENT LEVEL E2	REAR WINDOW: NON-HEATED REAR SCREEN	FUEL TANK CAPACITY: 100 LITRES TANK
LANE KEEP: W/O LANE DEPARTURE WARNI	LUGGAGE COVER: COMPLEMENTARY OBJECT	LIGHT PROTECTION: CONTEXT CRITERIOM
FRONT ARM REST: FRONT ARMREST TYPE1	TYPE OF CLIMATE: TEMPERATE CLIMATE	MUD FLAP: MUD-GUARDS WITHOUT FLAPS
INCREASED PAYLOAD: NORMAL PAY LOAD	DOUBLE TIRE: WITHOUT WHEEL COUPLED	ENGINE TYPE: 2.3 DCI DIESEL ENGINE
ADDITIONAL LOCK: CONTEXT CRITERIOM	SEAT REMOVABLE: SEAT NOT REMOVABLE	LUGGAGE RACK: COMPLEMENTARY OBJECT
TYPES OF RADIOS: RAD ENTRY DAB 4HP	POWER IN DIN HP / KW: 121 KW POWER	DUST PROTECTION: WITHOUT DUST KIT
SERVICE AHA: COMPLEMENTARY OBJECT	SERVICE TMC: COMPLEMENTARY OBJECT	CONDITIONING: STANDARD PROTECTION
WHEELS RIMS: COMPLEMENTARY OBJECT	REAR BODY SIDE: WITHOUT BODY SIDE	CAPACITY: GROSS VEH WEIGHT 3500KG
USE OF ALTERNATOR: ALTERNATOR 70A	RADIO COVER: COMPLEMENTARY OBJECT	NAVIGATION MAP: STANDARD MAPPING
REAR SCREEN BLIND: WITHOUT BLIND	TYPE OF HEADLIGHTS: HEADLIGHT 01	MODEL YEAR: COMPLEMENTARY OBJECT
FAST TRACK: COMPLEMENTARY OBJECT	FRONT SPOILER: CONTEXT CRITERIOM	STRIPPING: COMPLEMENTARY OBJECT
SPARE WHEEL: WITH A SPARE WHEEL	ECONOMIC DRIVING: WITH ECO MODE	TYPE OF FUEL OR ENERGY: DIESEL
TACHOGRAPH: WITHOUT TACHOGRAPH	PROTECTION ELEMENTS: DR AIRBAG	REAR OVERHANG: NORMAL OVERHANG
CRUISE CONTROL: CRUISE CONTROL	ROUTING SHEETS COUNTRY: POLAND	TRACK WIDTH: CONTEXT CRITERIOM
STEERING WHEEL POSITION: LEFT	REAR GATE: WITHOUT SIDE BOARD	BODY COLOUR: MINERAL WHITE BC
ENTRY GRIP: CONTEXT CRITERIOM	LUGGAGE BOX: W/O LUGGAGE BOX	TYPE OF TIRES: STANDARD TYRE
ROOF HUE: BODY COLOURED ROOF	LAYOUT: COMPLEMENTARY OBJECT	WHEELBASE LENGTH: LENGHT L3C
LADDER: COMPLEMENTARY OBJECT	TOW HOOK.: CONTEXT CRITERIOM	WINDOW TINT: TINTED WINDOWS
ROOF HEIGHT: HEIGHT ROOF 10	REAR BOX: CONTEXT CRITERIOM	BRAND DESIGNATION: RENAULT

BODYWORK TYPE: CAB CHASSIS	ENGINE SUFFIX: 708 INDEX	SEAT TRIMS: VELVET CLOTH
COUNTER UNIT: KILOMETRES	HORN: CONTEXT CRITERIOM	2ND ROW SEATS: WITHOUT
GLOVE BOX: GLOVE BOX 3	WHEEL TRIM: HUBCAP 01	

Archiwalne zdjęcia pojazdu

Sprawdzone, nie odnotowano danych

Zasady i warunki
Wszelkie informacje udostępnione za pośrednictwem serwisu autoDNA mają charakter informacji pomocniczych i stanowią jedynie wskazówki dla Użytkownika. Raport generowany jest na podstawie danych dostępnych w bazach autoDNA i rejestrach współpracujących z AUTODNA na moment wygenerowania raportu.

Własność intelektualna i autorska

- **Własność intelektualna i autorska:** Wszelkie treści i znaki graficzne zamieszczone w serwisie autoDNA chronione są prawami autorskimi przysługującymi AUTODNA Sp. z o.o. lub innym uprawnionym podmiotom.
- Wykorzystywanie treści lub znaków graficznych zamieszczonych w serwisie autoDNA jest dozwolone wyłącznie w zakresie określonym Regulaminem serwisu autoDNA lub bezwzględnie obowiązującymi przepisami prawa.
- AUTODNA Sp. z o.o. może posiadać patenty, zgłoszenia patentowe, prawa autorskie, znaki towarowe oraz inne prawa własności intelektualnej dotyczące treści udostępnianych za pośrednictwem serwisu autoDNA.
- Udostępnienie treści nie oznacza udzielenia licencji na patenty, prawa autorskie, znaki towarowe lub inne prawa własności intelektualnej w nich zawarte.
- Nazwy podmiotów lub produktów zawarte w treściach mogą stanowić zarejestrowane znaki towarowe lub znaki usługowe tych podmiotów.

Zasady korzystania i weryfikacja

- **Użytek własny:** Użytkownik może pobierać pojedyncze kopie materiałów wyłącznie do użytku własnego, w zakresie dozwolonego użytku osobistego określonego bezwzględnie obowiązującymi przepisami prawa, w tym w art. 23 ustawy z dnia 4 lutego 1994 r. o prawie autorskim i prawach pokrewnych (Dz.U. 1994 Nr 24, poz. 83, t.j. Dz.U. z 2025 r. poz. 24 ze zm.). Poza zakresem dozwolonego użytku osobistego zabronione jest powielanie, kopiowanie, przesyłanie, przechowywanie w systemach informatycznych, tłumaczenie na inny język oraz jakiekolwiek inne wykorzystywanie treści bez uprzedniej, wyraźnej zgody AUTODNA Sp. z o.o.
- **Narzędzie pomocnicze:** Informacje zawarte w raporcie stanowią jedynie narzędzie pomocnicze i wskazówkę.
- **Konieczność inspekcji:** Raport nie zastępuje fizycznych oględzin, jazdy próbnej ani weryfikacji stanu technicznego przez wykwalifikowanego eksperta lub w Autoryzowanej Stacji Obsługi (ASO).
- **Weryfikacja online:** Aby wyeliminować ryzyko modyfikacji raportu przez osoby trzecie, każdorazowo zalecamy sprawdzić jego oryginalność poprzez zeskanowanie kodu QR widocznego w nagłówku i porównanie danych z wersją online wyświetlaną w systemie autoDNA.

Regulamin Serwisu autoDNA dostępny jest w Serwisie Internetowym autoDNA.